



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
Report Date May 12, 2006

Supervisor DRH

**Mine Name:** Roudabush  
**Operator Name:** Worthen/Williams, LLC

**Permit number:** M0450027  
**Inspection Date:** April 6, 2006  
**Time:** 4:15-4:30 PM

**Inspector(s):** Paul Baker  
**Other Participants:** None  
**Mine Status:** Inactive at the time

**Weather:** Cloudy, light rain, 30's

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**  
This was a routine inspection.

**Inspection Summary:**

1. Permits, Revisions, Transfer, Bonds

In November 2002, the Division wrote the operator asking for a reclamation surety of \$97,800. This action was finalized in November 2005. On the normal five-year review schedule, the bond will be re-evaluated in 2007.


12. Other

The site was inactive at the time of the inspection, but the operator reported production in 2005. Equipment on site included conveyors and a front end loader. The attached photos show some of the product stockpiles and the highwall.

Inspection Date: April 6, 2006; Report Date: May 12, 2006  
Page 2 of 2  
M0450027

**Conclusions and Recommendations:**

I could see no environmental or public safety concerns at the mine site. On the road to the site, I found some Scotch thistle, and the operator should try to ensure it does not become established at the site.

Inspector's Signature  Date: 5/16/06

PBB:pb

cc: Robert Worthen, Operator

Attachment: Photos

P:\GROUPS\MINERALS\WP\M045-Tooele\M0450027-Roudabush\inspections\ins-04062006.doc



## ATTACHMENT

### Photographs

M0450027, Roudabush Mine, Worthen/Williams

Inspection Dated: April 6, 2006; Report Dated: May 12, 2006



**Photo 1. Some of the equipment at the mine.**



**Photo 3. Another view of the highwall.**



**Photo 2. Equipment and a portion of the highwall.**



**Photo 4. Some of the product stockpiles.**